ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE REGULATORY CONTACT RECORD

Date/Time:

02/02/05 - 1500

Site Contact(s):

K.W. Shuler (RFCSS) - (KWS-006)

Phone:

(303) 966-3423

Regulatory Contact: David Kruchek, CDPHE

Phone:

(303) 692-3328

Agency:

CDPHE

Purpose of Contact: Removal of Exterior Transite Windows from Ventilation Isolation Areas (VIA) 2 of Building 444

Meeting Attendance:

Harlen Ainscough, CDPHE

Gary Dreith, DOE

Dyan Foss, KH

David Kruchek, CDPHE Gary Morgan, DOE

Denise Onyskiw, CDPHE

Sam Garcia, EPA Duane Parsons, KH Sarah Roberts, DOE Karl Shuler, RFCSS

Mike Swartz, KH

Discussion

Building 444 (B444) has some windows with transite panels. Transite panels are nonfriable Category 2 asbestos containing materials (ACM) that must be removed prior to demolition. The overall plan is remediate the friable ACM, beryllium and radiological contaminants in the building's rooms so that the exterior transite panels can be removed, and the building structure can be demolished.

Friable ACM has been removed from VIA 2 of B444 and those areas have passed the final ACM air clearance sampling. Radiological surveys have confirmed that radiological (rad) contamination is less than action levels. Beryllium has been remediated in this VIA by fixation.

The PDS data provided indicates the area effected by the removal of these transite panels meets the unrestricted release criteria. Since the removal of the transite panels in VIA 2 will open those areas to the environment and survey data indicates that contaminants of concern are below action levels, the State (Kruchek) concurred that the panels could be removed prior to structure demolition. However, this concurrence is based upon the facility taking the following measures to prevent release of contamination to the environment while conducting all work activities:

Contact Record 02/02/05

1 0 2005

ADMIN RECORD

B444-A-000117

- 1. During the transite removal operations, appropriate IH and rad monitoring will be performed, as identified in the Work Plan.
- 2. Upon removal of the transite and exposure of uncharacterized surfaces, fixative will be applied to prevent possible release of contamination.

Contact Record Prepared By: K.W. Shuler

Required Distribution:	D. Kruchek, CDPHE	D. Shelton, KH
M. Aguilar, USEPA	J. Legare, RFFO	C. Zahm, KH
S. Bell, DOE	R. Leitner, KH	
R. Birk, DOE	J. Mead, KH	Additional Distribution:
C. Deck, KH	G. Morgan, DOE	H. Ainscough, CDPHE
D. Foss, KH	S. Nesta, KH	C. J. Freiboth, KH
S. Garcia, EPA	K. North, KH	D. Parsons, KH
C. Gilbreath, KH	S. Roberts, DOE	K. Shuler, RFCSS
S. Gunderson, CDPHE	R. Schassburger, DOE	M. Swartz, KH